

Rigidity analysis SSForm Order	analyze rigidity contacts				
	20	40	60	80	100
a1; b4; b3; b2; b1	99.7	99.6	99.9	99.9	0
b4; a1; b3; b2; b1	0	0.1	0	0	0
b4; b3; a1; b2; b1	0.3	0.3	0.1	0.1	100.0